



**TEST REPORT**

<b>Customer:</b> <b>M/s. RUSTCHEM CORROSOLS PRIVATE LIMITED</b> PLOT NO V 99, CHAKAN MIDC PHASE 2, NEAR GENERAL ELECTRIC LTD, WASULI, PUNE 410501	Report No.:	<b>H-22-6913-P</b>
	Report Date:	12-12-2022
	Job. No.:	ELP-22-23-21694
	Sample Received Date:	18-11-2022
	Date Of Completion:	12-12-2022
ULR No.:	TC574422000052013F	

**Customer Ref. No. & Date:** 0607/2022-23 16-11-2022

Samples not drawn by ELCA

**Product Specification:** --

**Sample Description:** Product Name : Rustchem ECOVCI Oil

**SALT SPRAY TEST**

<b>Discipline</b>	Chemical	<b>Group</b>	CORROSION TESTING
<b>Test Method :</b>	ASTM B117:2019		
<b>Tested At</b>	ELCA Quality System Pune	<b>Tested on :</b>	12-12-2022

Parameter	Result
Loading Date-	25.11.2022
Unloading Date-	12.12.2022
Protection/Coating-	Not Used
Method of Supporting-	Nylon Thread
Temperature within Exposure Zone °C	34.6 to 35.3
Exposure Period in hours -	400
Salt Solution concentration in % -	4.90 to 5.04
Type of Salt-	NaCl (AR Grade)
Type of Water-	Distilled Water (Type IV Grade)
Fog Collection Volume in ml/hr/80cm <sup>2</sup> -	1.4 to 1.9
Specific Gravity of salt solution-	1.030 to 1.035
Fog Collection pH-	6.88 to 7.07
Method of Cleaning-	Running Water
Period in Hours- 400	Observation No rust observed
Interruption in exposure-	Not Observed

Remark: Annexure Attached

\*\*\*\*\*END OF REPORT\*\*\*\*\*

**Checked By**  
Mohini Chavan

**Reviewed & Authorised by**  
**Authorised Signatory**

**S. B. DESHMUKH**  
(GENERAL MANAGER)





**SALT SPRAY TEST**

**ELCA Report No: H/22/6913/P**

**Date : 12.12.2022**

**Test Method : ASTM B117 (2019)**

**Annexure 1**



**(BEFORE HRS)**



**(AFTER 400 HRS)**

*Mohini Chavan*  
**Checked By**  
**Mohini Chavan**

*S. B. Deshmukh*  
**Authorized Signatory**  
**S. B. DESHMUKH**  
**(QUALITY MANAGER)**